## HANDLING POWER AND STEAM OUTAGE IN DCU RECENT EXPERIENCES

G D Vinothkanna – <u>vinothkanna gd@mrpl.co.in</u> Sudheer Pai – <u>SudheerPai@mrpl.co.in</u>





#### Contents

- Introduction
- Feed Characteristics
- Product Yield
- Major Challenges faced
- Power & steam failure @ switchover
- Power & steam failure after 3.5 hours of switchover
- Heater charge pump continuous cavitation



## Introduction

- DCU Capacity 3MMTPA
- Licensor Lummus technology
- 4 Drum operation with two heaters
- Commissioned on 02nd April 2014
- Turndown 50%
- Designed for coking cycle of 24 hours followed by a 24 hour de-coking cycle.
- Through Put Ratio = 1.10
- Design Feed TAN < 0.5%.



#### Feed Characteristics

S.NO	SPECIFICATION	DESIGN FEED CASE	Check case
1	Type of FEED stock	VR 550+ cut	560+
2	Feed rate (kg/hr)	375,000	3,70,000
3	API gravity	6.04	9.4
4	Viscosity	4040cst @ 120℃	1150 cst at 100 ℃
5	Sulfur content wt%	5.63	3.75
6	CCR, wt%	23.7	16
7	Asphaltene, wt%	19.6	11.0
8	Metals wppm (Nickel/Vanadium)	50 / 200	45/125



#### **Process Yield**

Products	Wt % Yield Design case
H <sub>2</sub> S	1.46
Off-gas	3.72
LPG	3.00
LN	3.98
HN	5.31
LCGO	30.67
HCGO	22.27
Coke	29.66



## Major Challenges faced

- 1. Power & steam failure at the time of switchover
- 2. Power & steam failure after 3.5 hours of switch over
- 3. Heater charge pump continuous cavitation
- 4. Coke drum MOV non operable fractionator and Blowdown tower first Mov
- 5. Hotspot/Steam/Coke bed collapse while cutting
- 6. Choking of DTM lines
- 7. Blockage of passage in water quench cycle



#### Power & steam failure @ switchover

Drum	Status at the time of power failure on 06 <sup>th</sup> Nov 2015 19.36 Hrs	
Drum A	Fully coked & switch over progress (70% towards A)	
Drum B	Vapour heated & switch over progress (30% towards B)	
Drum C	Cutting in progress	
Drum D	12 Hours Coking completed	



## Power & steam failure @ switchover (Cont..)

- 1. Total power and steam failure Emergency steam activated
- 2. More steam went to Drum B than A
- 3. HP 11kg/cm2 and and MP 3kg/cm2 after 1hr pressure normalized.
- 4. Switch valve rotated towards Drum B
- 5. Utility MP steam diverted to drum A 2T steam high feed line pressure)
- 6. Emergency steam have high T & P
- 7. Switch over to Drum A to B
- 8. Drum A water quench started at 00.30hrs 15M3/hr water -10.5 Kg/Cm2
- 9. After power clearance feed cut in done in Drum D @  $215^{\circ}$ C
- 10. Feed line pressure 4.6Kg/Cm2.



## Power & steam failure @ switchover (Cont..)

- 11. Heater B and Drum D stabilized.
- 12. Drum B feed cut-in done at 9.30hrs 35M3/hr
- 13. Drum A 150M3 water top water introduced 80M3/hr
- 14. Drum A skin 100 ℃ with 240M3/hr
- 15. 850M3 water filled ( 3M above coke bed height) soaking for a day
- 16. Drained to CCD to check any abnormality
- 17. Drained to maze floating with blowdown tower till bed height
- 18. Water refilling and draining done(4 times)
- 19. No abnormality found while draining Vent opened.
- 20. Cutting completed after 4 days of coking. Very fine powder coke observed.



#### Power & steam failure after 3.5 hours of switchover

Drum	Status at the time of power failure on 08 <sup>th</sup> Sep'15 21:03 Hrs	Status after power and steam clearance
Drum A	Coking cycle 3.5 hrs	Heater Emergency steam kept on to fractionator
Drum B	Fast water cooling since 1 hr	Fast water cooling resumed and completed by 05:00 hrs on 09/09/15
Drum C	Cutting in progress	Cutting completed
Drum D	13 Hours Coking	Fast water cooling started at 05:15 Hrs on 09/09/15 (After completion of Drum B)



#### Power & steam failure after 3.5 hours of switchover

- 1. Drum A Tarry drum
- 2. Power clearance after 1 hr
- 3. Emergency steam to Drum A to fractionator continued for 20hrs
- 4. VR circulation through heater B bypassing drum C/D started to increase fractionator bottom temperature 320 ℃
- 5. Heater A, Feed cut in done directly into Drum A without bypass

(keeping emergency steam on) at 18:30hrs on 09th Sep -15.

- 6. Initially feed line pressure increased to 4Kg/cm2 and soon got normal
- 7. COT increased and plant stabilized with heater A and Drum A.



## Heater charge pump continuous cavitation

#### Event 1 (16<sup>th</sup> Jan 2015)

- 1. During start-up WGC continuously surging and not able to load the compressor
- 2. Compressor suction pressure was varied to check compressor loading.
- 3. Compressor problem solved by changing the gas in the system and by controller reset.
- 4. Heater charge pumps were cavitating and lot of coke particle observed in strainer
- 5. Lot of coke observed in fractionator bottom filter in recirculation loop
- 6. Heater charge pump started and stopped for several times for evacuation of coke from suction



#### Event 2 (19<sup>th</sup> Feb 2015)

- 1. Both the heaters tripped with heater charge pump discharge pressure low low
- 2. Heaters were started with in 30min and heater pass flow increased to restore previous condition.
- 3. Heater A pass 1 skin temperature rapidly climbed to 668 °C with in 2 hours.
- 4. Some coils of Heater A were slagged and coil number 9 had a bulge at the middle
- 5. Replacement of coils done and unit restarted.



#### Event 3 (28th Feb 2015)

- 1. Heater charge pump discharge pressure collapsed and standby pump auto cut-in happened.
- 2. Both the heater got tripped due to pressure low low
- 3. Both the heaters started back and pump cavitated beyond 300M3/hr flow
- 4. Same condition observed in standby pump also.



#### Following action were initiated

- 1. Suction strainer of both pumps cleaned.
- 2. Flushing oil at the pump suction line blinded.
- 3. Back flushing with flushing oil system done to dechoke strainer and coke catcher
- 4. Fractionator bottom feed quality checked and found normal
- 5. Heater charge pumps MCF control valves checked and found ok
- 6. Pump suction pressure checked and found abnormal (350 M3/hr-1.15Kg/cm2 and 522M3/hr 0.95Kg/cm2 versus design 522M3/hr 1.41Kg/cm2)
- 7. Shutdown initiated and fractionator opened for inspection



#### Observation

- 1. Bottom section of the coke catcher crippled and there was no gap for liquid to flow at the bottom of the catcher.
- 2. Down comer pipes were broken and fallen down.
- 3. The chimney tray below wash grid had refractory damage.
- 4. Recirculation pump suction and discharge observed to be clean and intact.
- 5. Both HCGO wash header flanges gasket damaged



## Heater charge pump continuous cavitation-Root cause analysis (Cont..)

#### 1. Foaming in Coke Drums

- a. Higher viscosity and more coke bed height High coke carryover
- b. Antifoam dosing on time basis not on tendency of foaming
- c. VR from two wide range viscosity processed

#### 2. Pressure surge

- a. WGC surge while startup on 16<sup>th</sup> Jan leads to coke carry over to fractionator bottom.
- b. After plant startup frequent cleaning of charge pump suction strainer and tripping of heaters due to cavitation occurs.
- c. Coke catcher damage might initiated at this time.



## Heater charge pump continuous cavitation-Root cause analysis (Cont..)

#### 3. Feed Interruptions

- a. Feed interruption due to pump cavitation and localized heat flux leads to coke build up in heater coils
- b. Feed interruption leads to high skin temperature accelerate coke deposition in coils and shortening the run length of the heater











# Thank you

#### **Steam Eruption**

- 1. Shot coke Abnormal channeling prevents uniform cooling
- 2. Un even cooling Coke bed inside high temperature
- 3. Hot spot erupts violently when contact with water
- 4. Operating personnel exposed to high speed projectiles from the top flange