



# CASE STUDY DISTRIBUTION TRANSFORMER AND PD DETECTION

Charlie Smith, IAE Subject Matter Expert  
[Charlie@refiningcommunity.com](mailto:Charlie@refiningcommunity.com)



# INFORMAL RELIABILITY SURVEY

How old is your facility?

Less than 5 years old? 10 years? 20 years? Greater than 20 years?

Is your facility configured with single transformers supplying production critical loads?

Are your distribution transformers typically oil-filled or dry?

# INFORMAL RELIABILITY SURVEY

Which technologies does your facility use to determine health of your distribution transformers?

Dissolved Gas Analysis of Oil

Off-line insulation quality measurements

Infrared Scan

On-line partial discharge detection

Other?

Are you confident that someone in your facility understands the condition of your distribution transformers?

# CASE STUDY

1 MVA oil-filled transformer







2400 volt primary    480 volt secondary

Sole power supply for refinery Nitrogen production plant

Installation date August 2008


First indication of problem June 2010 in DGA

# CASE STUDY



JUNE 2010 DGA RESULTS

# CASE STUDY



JUNE 2010 DGA RESULTS







# CASE STUDY

## #1 Suspect – Tap Changer

1. Electrical field service contractor was on-site for TAR
2. Took transformer off-line
3. Opened upper inspection port and found a loose tap changer connection that showed signs of overheating
4. Fixed connection and placed transformer back into service
5. Problem solved - We thought




# CASE STUDY



JUNE 2011 DGA RESULTS

# CASE STUDY



JUNE 2011 DGA RESULTS

# CASE STUDY

Tested a new technology (new to the refinery):


In-Service Partial Discharge Tester

Uses a High Frequency Current Transformer clamped around the tank ground connection to detect PD

Test setup took about 10 minutes at the transformer

Immediately detected a waveform indicating arcing, not PD

# CASE STUDY



# CASE STUDY


Electrical field services contractor re-inspection two months later in October

Testing and a thorough visual inspection (included borescope) – nothing found


December DGA testing results were inconsistent

# CASE STUDY


**H<sub>2</sub>**




**CO**




**CO<sub>2</sub>**




**Methane**



**Ethane**




**Ethylene**



DEC 2011 DGA RESULTS

# CASE STUDY



DEC 2011 DGA RESULTS

# CASE STUDY

However, PD tests immediately following the inspection clearly detected the problem





## CASE STUDY

Conversations with the manufacturer were un-productive  
They were unfamiliar with field PD testing  
The gas levels did not yet concern them







Refinery personnel disagreed with them, and purchased a new transformer as an 'insurance policy'

No drop-in spare on site, and lead time a few months

## CASE STUDY


Subsequent DGA testing several months later also indicated the problem was still present.

# CASE STUDY



JUNE 2012 DGA RESULTS

# CASE STUDY



JUNE 2012 DGA RESULTS

## CASE STUDY

The new transformer arrived on site

A down-time window for the Nitrogen plant was a few months away.


The transformer was replaced and sent back to the manufacturer for autopsy and possible repair

# CASE STUDY

## Factory Findings


“multiple core ground points created different potentials, resulting in arcing between the core and frame, and from core to core across its insulation”

# CASE STUDY






# CASE STUDY




# CASE STUDY



# CASE STUDY

PowerHD Ver6.14.5 (R500K1) - Power HD Wave File Manager Point South 2.3.1 (C) 2011, 2012, 2013



# CASE STUDY

## Lessons Learned

Being newer does not guarantee a transformer's health

No one else is as concerned about our equipment as we are

A robust transformer inspection program should include on-line Partial Discharge testing