


Inspection Utilizing “Intelligent Pigging” of Coker Heater Coils



Author: Rich Roberts

FTIS™ Design Advancements

Generation #2



Generation #4




Generation #3




Generation #5

NextGEN FTIS

- 360 Degree UT Transducer array
- Increased sample frequency (40Hz → 100Hz)
- Increased memory storage (1 mile → 20 miles)
- Capable of inspecting piping sizes between 2.5" to 8.0"
- Capable of Negotiating Mule Ear (Plugged Header) returns
- Additional algorithms to further enhance data analysis process
- Anticipate 2nd - 3rd Qtr 2007



FTIS™ / LOTIS® Detectable Failure Mechanisms



Process Heater
Tube Rupture

Naphtha Hydrotreater


Pipe/Tube Wall Loss

- ✓ Corrosion (Int. or Ext.)
- ✓ Erosion (Int. or Ext.)
- ✓ Pitting (Int. or Ext.)
- ✓ Mechanical Damage (Int. or Ext.)


Deformation

- ✓ Bulging (i.e. Flame Impingement)
- ✓ Swelling (i.e. Creep Strain)
- ✓ Denting
- ✓ Ovality


Decoking Quality Control (Q/C) / Quality Assurance (Q/A)




Convection Pipe Studded / Finned Pipe




Corrosion (Convection Section Corrosion)




Corrosion (Convection Section Corrosion)





Flame Impingement Damage (Bulging / Swelling)





Dents In Pipe



LOTIS® Inspection of Furnaces Containing *Plugged Headers (Mule Ears)*



- LOTIS is capable of inspecting furnace coils which contain “Plugged Headers” (*a.k.a. Mule Ears*)
- Straight Section of Pipe is Inspected
- “*Internal*” flaws detectable and quantifiable:
 - ✓ Corrosion, Erosion, Pitting
 - ✓ Creep (Bulging / Swelling)




Case Study #1


CRUDE HEATER

- Number of Coils / Passes = 12
- Pipe Material = 9Cr – MO (A335-P9) (6” x Sch-80)
- Plant had several sections in which partial sections of piping coil had been replaced with new material.
- Plant Engineers did not expect any damage in new coil sections, however were concerned with older coil sections.
- Manual Ultrasonic inspection had not found any damage in previous years’ inspections (inspection limited to “only” Radiant section).
- A FTIS™ Inspection was carried out on all 12 coils/passses (Inspection encompassed “both” Radiant and Convection sections).
- FTIS™ data showed severe corrosion damage in “both” new and old coil sections.
- Plant has reconsidered use of conventional NDE inspection methods.

Case Study #1 Isolated Corrosion Damage



Case Study #1 Inspection Method Comparison




Case Study #2

VACUUM HEATER

- Number of Coils / Passes = 8
- Pipe Material = 5Cr (5", 6" & 8" x Sch-80)
- Plant had modified heater convection section. (*Installed soot blower*)
- During mechanical pig cleaning process water was observed coming from Convection Section.
- Plant then elected to have FTIS™ inspection performed, rather than start cutting off return bends to find damage.
- A FTIS™ Inspection was carried out on all 8 coils/passes (Inspection encompassed "both" Radiant and Convection sections)
- FTIS™ Intelligent Pig revealed only 8 pipe sections were damaged and localized to one end. All damage was "external".
- Plant stated that FTIS™ saved them over \$1M in coil replacement costs.


Case Study #2 Launcher / Receiver Set-Up



TYPICAL LAUNCHER / RECEIVER SET-UP




Case Study #2 FTIS™ Data Showing External Damage




Obvious Patterns Developing in Damage Distribution

Case Study #2 "Externally" Corroded Convection Piping



Case Study #2 Removed Piping From Convection Section



Case Study #2 Tube Repairs (1/2 New – 1/2 Old Material)






Case Study #3


ATMOSPHERIC HEATER

- Number of Coils / Passes = 4
- Pipe Material = 347Stainless (4", 5" & 6" x Sch-40/80)
- Plant anticipated damage, however nothing severe.
- FTIS™ Inspection revealed substantial damage in both Radiant and Convection sections of the coil.
- Plant cut out sections to confirm data. When the results matched perfectly, plant then elected to expand scope of work and inspect a total of three (3) heaters.
- FTIS™ data clearly showed two types of damage patterns.
- Plant cut out all damaged areas above threshold and confirmed accuracy of FTIS™. FTIS™ data matched destructive testing perfectly.
- Plant is now using FTIS™ data to better understand why damage is occurring.

Case Study #3 (3D Plot) Corrosion in Radiant Section Piping




Removed Pipe Coupons



Interior Pipe Surface Profile

Case Study #3 (2D Plot) Corrosion in Radiant Section Piping



Case Study #3 DESTRUCTIVE TEST RESULTS

PIPING COIL INSPECTION RESULTS CONFIRMATION

| | | | | |
|-------------------------------|-----|------------------------|-----|-------------------------|
| 1. PIPE # 11 - 150"-200" AREA | --- | FTIS™ REPORTED | --- | 0.096" (Remaining Wall) |
| | --- | MANUAL UT | --- | 0.095" (Remaining Wall) |
| | --- | DRILLED HOLE w/CALIPER | --- | 0.098" (Remaining Wall) |
| 2. PIPE# 11- 400"- 450" AREA | --- | FTIS™ REPORTED | --- | 0.097" (Remaining Wall) |
| | --- | MANUAL UT | --- | 0.110" (Remaining Wall) |
| | --- | DRILLED HOLE w/CALIPER | --- | 0.098" (Remaining Wall) |
| 3. PIPE # 28- 400" AREA | --- | FTIS™ REPORTED | --- | 0.247" (Remaining Wall) |
| | --- | DRILLED HOLE w/CALIPER | --- | 0.248" (Remaining Wall) |
| 4. PIPE # 29 - 200" AREA | --- | FTIS™ REPORTED | --- | 0.186" (Remaining Wall) |
| | --- | DRILLED HOLE w/CALIPER | --- | 0.188" (Remaining Wall) |


- THICKNESS CHECKS WERE INITIALLY PERFORMED BY FTIS™
- MANUAL UT THICKNESS WERE TAKEN ON EXTERIOR AFTER REMOVAL
- SAMPLES WERE CUT OUT / HOLE DRILLED AND MEASURED WITH A MICROMETER
ALL FTIS REMAINING READINGS WERE VERY CLOSE TO MICROMETER READINGS (+/- 0.002").
- THE AREAS SHOWING LOCALIZED THINNING IN THE FTIS REPORT HAVE EROSION AREAS THROUGHOUT ENTIRE PIPE LENGTH, WITH SCATTERED DEEPER PITTING.

Case Study #4


CRUDE FURNACE

- Number of Coils / Passes = 2
- Pipe Material = ASTM A-106, Grade B (6-inch x Sch.40)
- Plant did not anticipate any “serious” problems with heater prior to FTIS™ Inspection.
- FTIS™ was primarily being used to test technology and satisfy internal routine inspection.
- FTIS™ data results showed coil was exceptionally cleaned by “mechanical pigging” contractor.
- FTIS™ inspection results clearly showed extensive corrosion damage in the convection section.
- FTIS™ pointed out to plant that 6” x Schedule-20 piping was installed in the cross-over regions of the coil. “No” Schedule-40 as originally thought.
- Plant engineers later informed Quest TruTec that based upon the FTIS™ results they replaced coil.
- FTIS™ inspection potentially saved furnace failure.

Case Study #4 (2D Plot) Corrosion in Convection Section Piping



Case Study #4 (3D Plot) Corrosion in Convection Section Piping




Case Study #5

VACUUM FURNACE

- Number of Coils / Passes = 2
- Pipe Material = ASTM A335 – P5 (6-inch x Sch.40)
- Heater Vintage = 1976
- FTIS™ was applied to inspect both process coils.
- FTIS™ inspection results detected extensive “external” corrosion damage in the radiant section.
- Visual inspection found tightly adhered scale on piping exterior surface.
- FTIS™ results were not impacted by tightly-adhered scale.
- Large broad areas with 56% “external” wall loss were noted.
- Plant engineers utilized FTIS™ test results to make decision for replacement of several pipe sections.

Case Study #5 Corrosion in Convection Section Piping



Case Study #5 (3D Plot) Corrosion in Convection Section Piping

