

May 1, 2019

ExxonMobil Baton Rouge Refinery Coke Bed Combustion Incident

Sarah Whitaker – Resid Conversion Specialist
David Gibson – Fixed Equipment Specialist

Energy lives here™



Agenda

Introduction

Event Summary

Coke Drum Repair Strategy

Investigation Conclusions

Investigation Recommendations

Baton Rouge Coker Complex

- Baton Rouge – three Cokers, 10 drums
- Far East Coker – four drum coker, 1979 start-up
 - Bottom deheading – force actuated closure
 - Top deheading – manual unbolting with hydraulic swing back
 - Coke cut into pit, transferred to railcars, transported to barge loading



Event Summary


Stuck drillstem → Temperature increase → Drum failure

Timeline

- Circulated out of coke drum
- Quench, vent, and dehead drum without issue
- Pilot hole complete, drill stem becomes stuck while raising
- Coke drum temperature increases
- Drum integrity compromised, sparks observed falling from the drum – Emergency Response includes:
 - Top water
 - Rehead bottom and add quench water
 - Steam purge into top head space
- Drum decoke complete

Outcome

- No personnel injured or exposed
- Two through-wall holes formed near outage level
- Damage localized to drum
- Extended downtime to repair





Factors Contributing to Combustion

- Ignition source
 - Average layer AIT of petcoke dust <700F
 - Potential region of hot material in drum after quench
- Stack effect
 - Pilot hole provides ~4' diameter air ingress point, bottom head open
 - Multiple air egress points: open vent, drillstem guide plate
 - Bed cave in could resist flow, but is not airtight
 - Air density differential: ambient temperature near freezing, vapor space in head >150F
- Event drum operating conditions
 - Circulated furnace at end of cycle, material fed to drum at lower operating temperature
 - Ignition sensitivity increases with VCM
 - End of cycle material likely to deposit near top of drum

Drum Damage




Drum Damage




Coke Drum Repair Options

1. Local insert patch (~13'H x 24'W) deformed to match bulge profiles at ends.
2. Minimal height shell can (13'H) – leaving significant bulging.
3. 20' height shell can – removing fire related bulging/cracking.



Coke Drum Repair – 19'-10" shell can replacement



Schedule Optimization:

- Supported top head/shell from coke drum structure
- Installed curved monorail – minimized bull rigging
- Demo'd 19'-10" of shell vs panel replacement approach
- Installed bare C-1/2 Mo shell rather than clad or overlaid, future replacement previously scheduled
- Limited vertical weld seam thickness to 5/8", eliminating PWHT requirement and temper bead
- Protected vertical seam CA with Inconel WOL
- Allowed re-insulation prior to hydro coupled with NDE
- Temporary insulation vs permanent panels

Investigation Conclusions

- Extended exposure of coke bed to air allowed combustion event
 - Smoldering coke observed in past at lower severity
 - Risk assessments had not considered drum failure due to combustion
- Circulation event led to less-reacted resid feed and escalated severity
 - Drum did not meet site unreacted/green drum criteria
 - Circulation procedure followed
- Reduced quench water injection effectiveness
 - Normalized quench water volume below 5th percentile of recent operations
 - Minor mid-cycle temperature upsets – potential abnormal bed channeling
 - Increased probability of abnormally quenched coke

Investigation Recommendations

- Reduce frequency of delays while cutting
 - Improvements to cutting equipment and instrumentation
- Develop procedure for management of cycle delays
 - During quench – Do not drain, ensure water covers coke bed, open vent
 - While draining – Stop drain, do not dehead, refill with water, leave vent open
 - If drained and bottom deheaded – When delay exceeds 1 hour
 - Ensure telescoping chute is up
 - Start overhead water injection
 - Introduce water 15 minutes every 2 hours or continuously if drum draining
 - Visually check if drum is draining
 - Stop water if level detected above bed
 - Perform visual checks for smoke
 - Routinely reheading bottom not practical for Baton Rouge Cokers
 - For Cokers with bottom slide valves: option to close bottom and steam purge or refill with water

Questions?